

What's on this CD?

Antenna Test Selection Guide 5968-6759E

PNA support services

PNA-X and PNA Series Configuration Guide 5989-7606EN

2009 AD Symposium Antenna Test Presentation

85309A

85309A manual

85309A H20 manual

85309A H30 manual

85309A H40 manual

85310A manual

Instructions for replacing the BPF with a LPF

85320A/B Mixers

85320A/B Standard 2 – 26.5GHz mixers

85320A/B H20 .1 – 3GHz mixers

85320A/B H50 2 – 50GHz mixers

Amplifiers

87415A 87400A microwave Amplifiers 5091-1358E

Agilent 83000 series Microwave Amplifiers 5963-5110E

Antenna Test Application Notes

Antenna and RCS Configurations Using PNA

Antenna Calcs

Methodologies in Antenna RCS 5989-1937EN

ORFR-Theory - Antenna 101

Pulsed Antenna Measurements Using Agilent PNA 5989-0221EN

Triggering PNA Microwave Network Analyzers 5988-9518EN

Back to Basics

Back to Basics – Network Analysis

Phased Array

Radar

**Transmission line
Uncertainty**

Materials Measurements

**Free Space Seminar
Basics of Measuring Dielectric Properties 5989-2589EN
85071E overview 5988-9472EN**

Banded Millimeter

**Banded Millimeter-Wave Measurements 5989-4098EN
mmWave Technical Overview 5989-7620EN**

E836xC PNA and N5230C PNA-L

**E836x Technical Specs E8364-90031
E8361A C Specs E8361-90007
PNA L Series Technical Specs N5230-90020**

N5242A PNA-X

**Agilent PNA-X 5989-6154EN
Data Sheet and Tech Specs N5242-90007
Intermod PNA-X 5989-7265EN
N5242A_blk_2port
PNA-X Service Manual N5242-90001**

N5264A Measurement Receiver

**Antenna Calcs.xls
N5264A 03 09 Presentation
N5264A Data Sheet N5264-90003
N5264A Flier 5989-9639EN
N5264A_Block Diagram
N5264A help file**

PNA Block Diagrams

**Block Diagram N5230A blk_2port_passive
E8361A Block Diagram
E8361A_H11Block
E8362_3_4_H85 High Powered PNA**

E8362B Block Diagram
E8363B and E8364B Block Diagram
E8364C_Full_Block
N5242A_blk_2port
N5242A_blk_4port
N5264A_blk
N5264A_Block Diagram
PNA L Series 3- 2006 N5230-90002

Service Manuals

E8361-90001
E8364B H85
PNA B Service Manual 6-2006 E8364-90026
PNA L Series 3- 2006 N5230-90002
PNA-X Service Manual N5242-90001
Z5623A H83 Z5623_90070_book
Z5623A H84 Z5623-90066

Solid State Switches

N9397A C SS Switches 5989-3729EN
85331B 85332B SS PIN Switches 5989-4960EN
Agilent Solid State Switches 5989-5189EN
P940xA_C Pin Switches 5989-6695EN

Sources

E8257D PSG Configuration Guide 5989-1325EN
E8257D PSG Data Sheet 5989-0698EN
MXG Configuration Guide 5989-7753EN
N5183A MXG Data Sheet 5989-7572EN

Block Down-Converters

N5280/81A
Frequency Converter, 10 MHz to 26.5 GHz
User's and Service Guide
Frequency Converter, 10 MHz to 50 GHz
User's and Service Guide

