

	x=-12.5	x=0	x=12.5
y=0	800	500	800
y=7	250	350	250
y=14	50	100	50
7=19	25	35	25

Magnetic Field Intensity in Gauss Measured Above the Motor Magnet The Peak Field Occurs on the Surface of the Magnet

